



Your tax invoice.

Water pump replacement and minor service · 2017 Toyota Prado GXL 2.8 diesel (EK52PW)

PAYMENT STATUS
\$1,184.34 due
Due 06/11/2026

INVOICE DATE	DUE DATE	TERMS	JOB
23/10/2026	06/11/2026	Due within 14 days	JOB-1160

ISSUED BY	ISSUED TO	VEHICLE
Ironbark Diesel & Mechanical Pty Ltd Trading as Ironbark Diesel & Mechanical ABN 12 345 678 901 Repairer licence MVRL12345 (NSW) 14 Tannery Road, Tamworth NSW 2340	Tegan Holloway 0491 570 156	2017 Toyota Prado GXL 2.8 diesel Rego EK52PW Odometer 148,250 km

TAX INVOICE INV-1160 | TEGAN HOLLOWAY | EK52PW

DESCRIPTION	QTY	UNIT PRICE EX GST	GST	GST AMOUNT	AMOUNT INC GST
WATER PUMP REPLACEMENT					
Replace water pump and drive belt Flush, refill and bleed the cooling system	2.5	\$150.00	10%	\$37.50	\$412.50
Water pump and gasket kit - Prado 2.8 diesel	1	\$289.00	10%	\$28.90	\$317.90
Drive belt 7PK - Prado 2.8 diesel	1	\$86.67	10%	\$8.67	\$95.34
Toyota pink premix coolant 5 L	2	\$38.50	10%	\$7.70	\$84.70
MINOR SERVICE					
Minor service Oil and filter, fluids, tyres, brakes and lights checked	1	\$249.00	10%	\$24.90	\$273.90

HOW TO PAY		SUBTOTAL (EX. GST)	\$1,076.67
Name	Ironbark Diesel & Mechanical	GST (10%)	\$107.67
Account	1234 5678		
BSB	123-456	TOTAL (INC. GST)	\$1,184.34
Reference	INV-1160		

NOTES	
Water pump replacement and minor service	
Found	Coolant leaking from the water pump, with residue down the front of the engine and on the drive belt. The pump gasket had failed.
Done	<ul style="list-style-type: none">Replaced the water pump and gasketReplaced the drive belt, which was soaked in coolantFlushed, refilled and bled the cooling system with Toyota coolantChanged the engine oil and oil filter
Checked	No leaks at operating temperature. Cooling fans working correctly.
Next	Please check the coolant level over the next week.